

K102539 ICUFF REPAIR PLATE, RIGHTFeb 24, 2011
174 days to decisionK102539 · Product code: **MBI** · Orthopedic
Source: <https://www.510kdatabase.net/k102539/>**SUBMISSION DETAILS**

Decision	Substantially Equivalent (Cleared)
Submission type	Traditional
Device classification	Fastener, Fixation, Nondegradable, Soft Tissue (MBI)
Date received	Sep 3, 2010
Decision date	Feb 24, 2011
Days to decision	174 days
Third-party review	No
Summary / Statement	Summary
Other names	CUFF REPAIR PLATE. LEFT; ANCHOR BOLT, 10MM THROUGH 50MM

APPLICANT

Company	Shoulder Options, Inc.
Location	Waxhaw, NC, US
Contact	JOHN KAPITAN
510(k) history	3 submissions · 3 cleared · 2011-2014

510k Database - www.510kdatabase.netDevice record: <https://www.510kdatabase.net/k102539/> Data sourced from FDA 510(k) public records (accessdata.fda.gov).510k Database is an independent platform not affiliated with the U.S. Food and Drug Administration. Always verify at accessdata.fda.gov. - Generated May 14, 2026