

K103762 SORIN C5 SYSTEMJan 20, 2011
28 days to decisionK103762 · Product code: **DTQ** · CardiovascularSource: <https://www.510kdatabase.net/k103762/>**SUBMISSION DETAILS**

Decision	Substantially Equivalent (Cleared)
Submission type	Special
Device classification	Console, Heart-lung Machine, Cardiopulmonary Bypass (DTQ)
Date received	Dec 23, 2010
Decision date	Jan 20, 2011
Days to decision	28 days
Third-party review	No
Summary / Statement	Summary
Other names	85/C5 MAST ROLLER PUMP SYSTEM 150(1X RP 150 AND CONTROL PANEL WITH CONNECTING CABLES); S5/C5 MAST ROLLE

APPLICANT

Company	Sorin Group Deutschland GmbH
Location	North Attleboro, MA, US
Contact	ROSINA ROBINSON, RN, MED, RAC
510(k) history	20 submissions · 20 cleared · 2006-2017

510k Database - www.510kdatabase.netDevice record: <https://www.510kdatabase.net/k103762/> Data sourced from FDA 510(k) public records (accessdata.fda.gov).510k Database is an independent platform not affiliated with the U.S. Food and Drug Administration. Always verify at accessdata.fda.gov. - Generated May 24, 2026